

# FILL ADAPTER INSTRUCTION SHEET

MODEL # WBFA-3, WBFA-45



**TURANAIR™**  
• SYSTEMS, INC. •

www.turanairsystems.com

The Fill Adapter is used to transfer up to 4500psi compressed air into any 4500 psi approved T-FORCE™ Work Bottle™ from a commercial high-pressure compressor such as Scuba/Dive shops, Fire Stations, Marinas (that fill dive tanks), Paintball fields and stores, Air Gun stores, Hydrostat testing facilities, etc. Your Work Bottle™ CANNOT be filled from these locations without the Fill Adapter.

Fill Side



Lock Down Side



**A: Quick Connect Couple;** Connect to Fill Port on the (left side) Regulator.

**B: Air Intake Port;** 4500psi rated stainless steel block. Connect to a commercial compressor fill apparatus.

- **WBFA-3;** is used and rated to fill up to 3000 psi.
- **WBFA-45;** is used and rated to fill to 4500 psi.

## NEED TO KNOW:

- ✓ The label on your bottle/tank gives all the information needed to accept your bottle/tank for a fill.
- ✓ Any refill location will check to see that your bottle/tank is hydrostat tested and when it needs to be certified again before filling.
- ✓ You do not have to disconnect the air hose in order to fill the Work Bottle™.
- ✓ Give them the Fill Adapter and your Work Bottle™ and they will fill it for you.
- ✓ If there are any problems with the Fill Adapter, DO NOT attempt to fix it yourself. This will void your warranty. Contact the Service Department at 1-888-903-4247.

## WHAT TO ASK:

- ✓ Make sure they can fill to your psi needs first, whether it is 3000psi or 4500psi.
- ✓ Ask about their timing. Some locations have you leave it overnight and some can do it right away.
- ✓ Ask about their fees. Usually it is very minimal.